



ADATA

Firmware Release Notes

Version 1.0

WARNING:

This firmware release is only valid for
ADATA SX910/SX900/SP900/SP800/S511/S510/S396 Solid State Drives
Firmware Version 5.0.2a
July 31, 2012



Issues resolved:

Item	Description
1	Improved the handling of a COMRESET command during AHCCMDT testing
2	Improved the hardware handling when it takes too long to resume from partial to slumber state
3	Fixed an issue that could cause the extraction of a panic dump to be corrupted based on a CRC error
4	Fixed an issue that can cause a flash command to time out
5	Fixed the handling of the internal read buffers when reporting UECC errors
6	Fixed an issue causing incorrect block P/E counts due to abnormal amounts of secure erases